

Redco™ Bolt Together Idler Sprockets

Eliminate Premature Chain Wear

Redco™ 750 bolt together idler sprockets are a quick and easy fix to sprocket replacement frustrations, particularly in the middle of a shaft.

The split “C” hubs are manufactured to fit any of the “A” plates for an easy mix and match. If you wear out the hub, simply unbolt the old one from the A plate and bolt on the new hub. A quick changeout that saves you the expense of having to purchase a whole new sprocket.

As well as being lightweight, Redco™ 750 sprockets will reduce or eliminate wear on the barrels and side links of the chain and also reduce noise levels.

The split “C” hubs are available in four common shaft sizes, 1 15/16”, 2 3/16”, 2 7/16” and 2 15/16” and come complete with a grease groove and fitting. The “A” plates are available in 10 - 15 tooth for both 81X and H78 chains, and can be ordered in split or solid.

Contact us for pricing and more information.



- Quick & Easy Replacement
- Lightweight
- Long-Wearing
- Split or Solid “A” Plates

Mix & Match “C” Hubs with “A” Plates

Split “C” Hubs

Part #	
R-7323A	1 15/16” shaft
R-7323B	2 3/16” shaft
R-7323C	2 7/16” shaft
R-7323D	2 15/16” shaft

All “C” Hubs are 3 7/8” LTB

“A” Plates

Part #	
R-3692A	10 tooth
R-5502A	11 tooth
R-3879A	12 tooth
R-5503A	13 tooth
R-3707A	14 tooth
R-4479A	15 tooth



CDN 1 800 667 0999 US 1 866 733 2684
sales@redwoodplastics.com
www.redwoodplastics.com